



Wiring Diagram




Butt Splice (IDC) Connector




Using crimper or pliers and pressing the header of connector down to even position

Copyright © All rights reserved.
P-MU-CT-PBT200-4 Ver.B Publish: 2011.08.11

Wiring Diagram




Butt Splice (IDC) Connector




Using crimper or pliers and pressing the header of connector down to even position

Copyright © All rights reserved.
P-MU-CT-PBT200-4 Ver.B Publish: 2011.08.11

Wiring Diagram



Butt Splice (IDC) Connector



Using crimper or pliers and pressing the header of connector down to even position

Copyright © All rights reserved.
P-MU-CT-PBT200-4 Ver.B Publish: 2011.08.11