

# Electric Strike Installation Instruction GK1100 Series

### Wiring Diagram GK1100 series is polarity insensitive




#### **Surface Mount Installation**




## Reversible from Fail-secure to Fail-safe

Loosen screw #1 first. Loosen screw #2 and fix it to the other end. Fix screw #1 next to its original place.



## **Butt Splice (IDC) Connector**



Place the wire inside the connector and use a crimp or pliers to press down on the head of the connector evenly.